
## Beaufort Chukchi Sea Utqiagvik Seward Peninsula Strategies Kodiak Bering Island Gulf Sea Aleutian Alaska Islands ponse Location of NE-28 Map & Photo es Geographic Columbia Bay Island; View South Free-oil Skimming and Recovery, Shallow Water **Deflection Booming-Live** DF-L **Protected-water Boom**

## Columbia Bay Island, PWS-NE28



ID	Location and Description	Response Strategy	Implementation	Response Resources	Staging Area	Site Access	Resources Protected (months)	Special Considerations
NE-28-01	Columbia Bay Island	Free-oil Recovery	Deploy free-oil recovery strike teams upwind and up current	Deploy multiple free-oil recovery strike teams as	Valdez Harbor	Via marine waters	Same as NE-28-02	Vessel master should have local knowledge.
FOS	Nearshore waters in the general area of:	Maximize free-oil recovery in the offshore & nearshore environment of Columbia	of Columbia Bay Island.  Use aerial surveillance to locate	required to maximize interception of oil before it impacts sensitive areas.		Chart 16708-1		Use extreme caution, shoal waters with numerous reefs
	Lat. 61° 02.33' N Lon. 147° 01.016' W	Bay Island depending on spill location and trajectory.	incoming slicks.					and rocks.
NE-28-02	a. Lat. 60° 00.219' N	Deflection-Live Using fishing vessels to hold	Place boom and hold in place with fishing vessel (Class <sup>3</sup> / <sub>4</sub> ).	<b>Deployment Equipment</b> 1500 ft. protected-water boom	Vessel platform	Via marine waters	Marine mammals- seals, otters	Vessel master should have local knowledge.
DF-L	Lon. 147° 01.006' W	the boom in place, deflect oil from Columbia Bay Island and back into the channel for free-oil recovery.	Position boom at a proper angle to deflect oil from the island creates by the terminal moraine in Columbia Bay and	Vessels 3 ea. class 3/4  Personnel/Shift		Chart 16708-1	<b>Birds</b> -waterfowl concentration, seabird nesting	Vessel master should have local knowledge.  This strategy can only be used
		fice-on recovery.	the nearby rocks.	9 ea. vessel crew			Habitat- sheltered rocky shoreline, gravel	in calm or moderate conditions and when the
			Tend throughout the tide.	Tending Vessels 3 ea. class 3/4			beaches	glacier ice is in the back of the bay.
				Personnel/Shift 9 ea. vessel crew				This island does not appear on current charts.
								Highly active seabird rookery with thousands of seabirds in the area.
								Surveyed: 09/07/2017 Tested: 09/07/2017 SERVS deployment